

Council, November 2015, Answer to Question 7 - LIST OF WORKS.

Beam River	Main River	EA weir removal Routine maintenance	Summer 2013
Blacks Brook	Main River	Routine maintenance	All 2015
Broxhill Drain	Ordinary Water course	Tree root mass removal. Dredging /clearance of channel. Routine maintenance	Autumn 2014 All 2015
Carter Brook	Main River	Routine maintenance	All 2015
Emerson Park Stream	Main River	Dredging on main river. 25 tonnes of silt removed. Routine maintenance	Summer 2015 All 2015
Havering Country Park -	LBH / Riparian Owner	Complete clearance of channel and new pond introduced. Routine maintenance	Autumn 2014 All 2015
Pinewood Road		Culvert renewal/upsized under private road. Routine maintenance	Autumn 2014 All 2015
Ingrebourne Branch Drain	Main River	EA completed culvert survey. Requires clearance. Programmed for 2016.	Spring 2014 Quote obtained

Council, November 2015, Answer to Question 7 - LIST OF WORKS.

Ingrebourne River	Main River	Dredged from Bridge Road to sewerage works by EA. Water level investigation and survey by EA underway Routine maintenance	Autumn 2014 On going All 2015
Orange Tree Hill	LBH / Riparian Owner, Culvert and open ditch. Ordinary Water Course	Clearance of blockages by LBH by privately owned. Requires enforcement action. Routine maintenance	Spring 2014 All 2015
Paines Brook	Main River	Fallen trees removed. Routine maintenance	Spring 2015 All 2015
Rainham Creek	Main River	Routine maintenance	All 2015
Ravensbourne River	Main River	Mass silt trap cleared Routine maintenance	Sept 2015 All 2015
Rise Park Drain	LBH Ordinary Water course	Collapse Sewer repair (repair by LBH). Tree root mass removal. Dredging /clearance of channel. Routine maintenance	Summer 2014 All 2015

Council, November 2015, Answer to Question 7 - LIST OF WORKS.

Rom River	Main River	Invasive species treatment at Cedar Close. Blockages removed. Fallen trees removed. Routine maintenance	Sept 2015 Summer 2014 Summer 2014 All 2015
Roneo Corner Bridge	Main River	New development channel realignment. Routine maintenance	Oct 2015 All 2015
Upminster Bridge	Main River	Routine maintenance	All 2015
Warley-D-Brook	Riparian Owner	Routine maintenance	All 2015
Weald Brook	Riparian. Ordinary water course	Routine maintenance	All 2015
Garland Way	Surface water balance tank LBH	Routine maintenance	All 2015
Marshall Drive,	Stream LBH and land owner	Routine maintenance Outstanding works to clear debris. Entrance now gated by residents due to ASB.	Unable to gain access due to residents

Routine maintenance involves physical inspection then subsequent removal of any blockages, fly tipping removed, bank repairs and silt depth assessment and foliage assessment/cut back.
Assessment of evasive species.

TWU headwall clearance if necessary and liaison with all external partners